UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,385,716 B1 APPLICATION NO. : 09/388891

DATED

: June 10, 2008

Page 1 of 2

INVENTOR(S) : Claus Skaanning

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 27, after "a" delete "is". In column 13, line 38, after "the" delete "8d". In column 13, lines 38, above "9" insert -- 8d --. In column 16, lines 22-48, below "TABLE 8" delete

		Yes	No
1)	Media 12		
2)	Paper path diny	22	
3)	Environmental conditions	ė	
4)	ione: sutridge problems	35	()ناو د
	a) Defective touer carridge	10	
	b) improperly sented toxes cantridge	5	
	c) Toner distribution	8.5	->25
5)	Transfer roller problems	20	
	a) Defective or dirty transfer rotter	2.5	
	b) improperly sented transfer roller	65	
	6) Worn out treasfer roller	171	
6)	Incorrect application senings	4.5	
	a) Bennomodo/draft mode on	7.5	
	b) 300/600 dpi set to 300 dpi	1.5	
	c) Other sertings set wrong	10	
7)	Incorrect printer driver settings	27	
	a) Reonomode ser on	80	
	b) 300/600 dpi set to 300 dpi	15	
	c) Other settings set wrong	.5	
8)	incorrect control panel settings	5 2 85	
	a) Beonomode draft mode set on	8.5	
	 b) 300/600 dpi set to 300 dpi 	5	
	c) Print density set too low	10	
9)	Corrupt data flow	1	
(O)	Wrong driver used	1.5	
(1)	Other problems	10	
	a) Temporary problem	10	
	b) Fermanem problem	90)	

and insert

- ,	Media 12			Xes	Ma
ż		22			
	Environmental conditions	6			
4	Toner cartridge problems	35		->90	
•	a) Defective toner cartridge	Gu	10	-2341	•
	b) Improperly seated toner cartridge		5		
	c) Toner distribution		85		->25
5	Transfer roller problems	20	GG		-740
***	a) Defective or dirty transfer roller	Lu	25		
	b) Improperly seated transfer roller		65		
	e) Worm out transfer roller		10		
R) Incorrect application settings	45	10		
•	a) Economode / draft mode on	40	75		
	b) 300 / 600 dpi set to 300 dpi		15		
	e) Other settings set wrong		10		
7) issurrect printer driver settings	27	40		
-	a) Economode set on	2,	80		
	h) 300 / 600 dpi set to 300 dpi		15		
	c) Other settings set wrong		δ		
8	Incorrect control panel settings	2	U		
•	a) Economode / druit mode set on	_	85		
	b) 300/600 dpi set to 300 dpi		ō		
	c) Print density set too low		10		
9	Corrupt data flow	,	10		•
	O) Wrong driver used	16			
	1)Other problems	10			
•	a) Temporary problem	217	10		
	b) Permanent problem		90		, therefor.
	o) Astronomy problem		30		, therefor

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,385,716 B1

Page 2 of 2

APPLICATION NO. : 09/388891

DATED INVENTOR(S) : June 10, 2008 : Claus Skaanning

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 18, line 44, delete " C_{ix} =yes" and insert -- C_i =yes --, therefor.

In column 21, line 8, delete "A1" and insert -- A1 --, therefor.

In column 21, line 9, delete "A2" and insert -- A2 --, therefor.

In column 30, line 23, after "that the" delete "action".

Signed and Sealed this

Fourteenth Day of October, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office